



**Government Of West Bengal**  
**Office Of The Deputy Director**  
**West Bengal Fire & Emergency Services**  
**Station Feeder Road, P.O & P.S Siliguri,**  
**District: Darjeeling, Pin - 734005**

Memo no.:IND/WB/FES/20192020/83009

Date: 21-02-2022

**From:**  
**Deputy Director**  
**North Zone, HQ Wing,**  
**West Bengal Fire & Emergency Services**

**To: PRINCIPAL KENDRIYA VIDYALAYA COOCH BEHAR**  
**NILKUTHI,BABURHAT,PS-KOTWALI,DIST- COOCH BEHAR,WEST BENGAL**

**Sub: Fire safety Certificate for an existing construction of G+1 storied school building under group Educational and represented by Mr. Reji V R Nath in respect of " PRINCIPAL KENDRIYA VIDYALAYA COOCH BEHAR " at the premises no- Mouza- Kharimala Khagrabari, J . L . No- 125, Plot NO- 1354, 1355 , 1361 , Nilkuthi, Baburhat, PS- Kotwali, Dist- Cooch Behar, Pin No-736156.**

This is in reference to your application no. 0125189210400042 dated 26-12-2021 regarding the Fire safety Certificate for an existing construction of G+1 storied school building under group Educational and represented by Mr. Reji V R Nath in respect of " PRINCIPAL KENDRIYA VIDYALAYA COOCH BEHAR " at the premises no- Mouza- Kharimala Khagrabari, J . L . No- 125, Plot NO- 1354, 1355 , 1361 , Nilkuthi, Baburhat, PS- Kotwali, Dist- Cooch Behar, Pin No- 736156.

The performance of the Fire Fighting System as incorporated in the buildings were tested at random and found satisfactorily working condition. In view of the above this office is releasing the Fire Safety Certificate for occupancy of the aforesaid building.

**Recommendation:**

- 1.As per fire safety recommendation one terrace level pump needs to be incorporated with the over head reservoir to the down comer system provided in the building.
- 2.Driveway must be free from any type of obstruction for easy movement of fire appliances. No parking will be allowed on the drive way of the school building.
- 3.The internal finish decoration of the building shall be made low flame spread conforming I.S. specification .
- 4.To eliminate risk of fire hazard , good house keeping both for inside and out side the building shall be strictly maintained.
- 5.Existing electrical wiring of the building shall have to be carefully checked wear and tear in them , particularly lines above false ceiling and ducts .
- 6.A fire control room including a closed circuit TV system will have to be maintained observe all floor of the building .
- 7." No Smoking " board should be displayed .

- 8.The employees and security staff shall be conversant with installed Fire Fighting equipment's and to operate in the event of Fire and testing.
- 9.Regular Mock fire practice and evacuation drill shall be performed periodically with all employees of the building .
- 10.First Aid Fire fighting system shall be provided as per I.S. specification.
- 11.A crew of trained fireman under an experienced officer shall be maintained round the clock for safety of the building .
- 12.The notice of fire fighting and evacuation from the building shall be prepared and displayed at all venerable places of the building.
- 13.If required old line shall have to be replace with new lines, the cable shall always in M.S. conduit pipes continuously bonded to the earth.
- 14.The fire safety audit to be conducted a regular interval and to be recorded in the fire prevention maintenance register .
- 15.Fire license shall have to be obtained for storing and processing with L.P.G. and others highly combustible articles.
- 16.This Fire Safety Certificate is valid for three ( 03 ) years and has to be renewed after three years from the date of issue of this certificate as per notification Govt. of West Bengal vide Notification No- 629-L, Dated- 17/04/2018 , Certifying about the satisfactory services , Performance of all life and fire safety arrangement of the building.

Deputy Director  
West Bengal Fire & Emergency Services

Memo No.:IND/WB/FES/20192020/83003